

This hole should  
be moved here.



(1) M3 X 6 shcs

Brushless Motor Mount  
w/ support

(3) M3 X 10 shcs